

PROJECT SUMMARY

Funding


- Funding Request of \$1,100,000
- Project includes the replacement of elevated boardwalks along the Davis Simpson Trail and replacement of the paddle craft landing and pavilion.


Current Status

- The boardwalks are in need of maintenance to bring them to current ADA standards.
- Structural damage has been caused by tidal water action. New standards & materials will hold up better in the future.

Impact on Tourism

 Replacing the boardwalk allows continued ADA public access to 1.25 miles of trails within the natural mangrove canopies and hammocks.





PHASE 1

 Wooden boardwalks constructed to connect dirt paths; beginning at the entrance of the preserve through the Smith Trail to the pavilion and kayak launch.



PHASE 3 & 4

Replacing boardwalks, kayak launch and pavilion from the entrance through the Smith and Davis Simpson Trails.

PHASE 2


 Connect various sections of approximately 375 linear feet of ADA compliant boardwalk that ties to phase 1.

BUDGET

Fiscal Year	Budget	Expenses	
FY 16/17	\$185,000	\$3,620	Design
FY 17/18	\$35,000	\$48,606	Design & Permit
FY 18/19	\$405,015	\$19,631	Design & Permit
Totals	\$625,015	\$72,057*	

^{*}expenses to date with an additional \$22,039 encumbered

Project
625,015.00
72,057.25
22,039.00
530,918.75
1,100,000.00
1,630,918.75
1,725,015.00



Estero Bay Mail Gressman Alsop Entrance Myers Loop Estero Blvd. PROPOSED 11'x26' **OBSERVATION PIER** PROPOSED FLOATING KAYAK LAUNCH PROPOSED 6' WIDE **BOARDWALK** MATANZAS PASS PROPOSED 6' WIDE **BOARDWALK** PROPOSED BENCH-PROPOSED 6 WIDE BRIDGE PROPOSED 10' WIDE BOARDWALK PROPOSED 10' WIDE BRIDGE PROPOSED 10 WIDE BOARDWALK

TIMELINE

- Design will be completed during the Summer of 2019.
- Approving the funding will allow the bidding process to start this summer and construction to begin in September 2019 and take 4-6 months to complete.
- Due to the remote location of the preserve, materials must be transported using small equipment and/or carried in manually by workers.